

Quickstart description

R-iZ0®

- 1 Check the delivery for transport damages and completeness.
- 2 Tack the lightmodules together underneath your containers. Lightmodules have the R-iZ0 logo printed on.
- 3 Fill up the gaps with bridge- or cablemodules.
- 4 Tack a connectingmodule at the end of each module-row. The connectingmodules' cable is tacked with the basismodule. Put the power supply through the basismodule and tack in the barcodescanner – ready to start.


1



2



3



4



Note: You will find more information in our guide or on our website: www.r-izo.de/doku.htm

